




# Installation Instruction

7/8 EIA connector for 7/8" air cable

1. Strip the cable jacket according to below dimension;




2. Slide sealing ring onto the cable, then screw the back nut onto the cable;



3. Flaring the cable using special tool (Below picture for ref.)



Special flaring tool



Flaring



After Flaring

4. Squeeze the copper by special tool.



Squeeze tool



Squeeze the cable



After squeeze

5. Fix shell 1 with wrench 32#, rotate shell 2 with wrench 32#, make it tight; Then measure the interface of connector

